

川崎製鉄(株) 千葉製鉄所 ○柿原節雄 馬田 一

浜上和久 久我正昭

技術研究所 吉井 裕

1. 緒 言

連続铸造の非定常部、とりわけ取鍋交換などの継目铸片の清浄度が悪いことはよく知られている。そこで、75 ton の大容量 タンディッシュを有する千葉 No.3 連铸機において、介在物の起源調査と、これに基づいた各種の対策を実施した。その結果について報告する。

2. 介在物起源調査

非定常部铸片の介在物起源調査のため、トレーサーとして取鍋スラグ、タンディッシュフラックス、モールドパウダーに、それぞれ BaCO₃, La₂O₃, CeO₂ を添加し、铸造中の タンディッシュフラックスやモールドパウダーおよび铸片内介在物の組成変化、さらには、介在物量の調査を実施した。铸片内介在物中に認められたトレーサー成分の分析結果を Table 1 に示す。これより、継目铸片内に認められる介在物の起源は、タンディッシュフラックスの寄与の大きいことがわかる。次に定常部と継目の、取鍋内とタンディッシュ内の溶鋼中の介在物量を Fig.1 に示す。介在物は定常部と比較して継目に多い。Fig.2 にはタンディッシュ内と铸片内の介在物量を示す。铸片中の介在物の量は、一般的深絞り用冷延钢板では製品品質上、問題ないレベルであるが、DI 缶クラスの超清浄鋼においては、継目铸片で介在物限界量を超える場合がある。

3. 介在物低減対策

トレーサー実験から、継目铸片内の介在物の中にタンディッシュフラックスが多量に混入していることが明らかになつた。その防止対策として、タンディッシュ堰形状の改善や浸漬開孔可能な取鍋ロングノズルを開発し、DI 缶クラスの清浄鋼の铸造に採用した。その結果、Fig.3 に示すように、製品における磁粉探傷(MT)結果は、継目铸片においても、定常部と同等の品質レベルが得られた。

4. 結 言

継目铸片中の介在物の起源を明らかにした。また、超清浄鋼の製造において、継目部も、定常部と同等の品質が得られる技術を確立した。

(参考文献)

1) 飯田ら: 鉄と鋼 64(1978)S148 2) 吉井ら: 鉄と鋼 64(1978)S626 3) 上田: 公開実用 昭和 57-127360

Table 1 Example of chemical composition of inclusions in slab and tundish flux (wt %)

Tracer Slab	Inclusions in slab			Tundish flux	
	CeO ₂	La ₂ O ₃	BaO	La ₂ O ₃	BaO
Middle	0	0.87	0.07	6.73	0.20
Ladle change	0	1.70	0.16	5.90	0.34




Fig. 1 Relationship between index of amount of large inclusions in tundish and that after RH treatment




Fig. 2 Relationship between index of amount of large inclusions in slab and that in tundish




Fig. 3 Transition of MT defects of cold sheet