

## Contents

### Special Issue on "Bolted Connections and High Strength Bolts"

High Strength Bolted Connections in Steel Structures (Review)	
A. TANAKA .....	587
A New Design for Bridge Joints Using High Strength Bolts (Review)	
K. SHITO and N. SUZUKI .....	593
Bolt Steels Used for Steel Structures (Review)	
Y. NAMIMURA .....	600
Delayed Fracture of Bolts (Review)	
F. NAKASATO .....	606
Evaluation Method of Delayed Fracture Property and Overcoming Techniques of Delayed Fracture of High Strength Steels (Review)/T. TARUI and S. YAMASAKI .....	612

### Fundamentals of High Temperature Processes

Development of Non-contact Electromagnetic Sensor for the Meniscus Velocity Measurement of Molten Metal Flow/M. IGUCHI, K. HANAZAKI and Y. TERAUCHI .....	629
Development of the Recycling Process of Automobile Shredder Residue by Coal-tar Based Oil Bath Treatment/I. UENO, M. ASANUMA, H. HIROHA, T. OKADA, T. ARIYAMA and K. WAKIMOTO .....	635
Interaction between Water-Air Bubbling Jet and Side Wall of Vessel (Note)	
M. IGUCHI and K. SASAKI .....	699

### Chemical and Physical Analysis

Inclusion Inspection Method in Ultra-sonic Fatigue Test	
Y. FURUYA, S. MATSUOKA and T. ABE .....	643
Analysis of Chemical Reaction in the Voids of Cokes Using NMR Gas Imaging	
K. SAITO, K. KUNITOMO, K. FUKUDA, K. KATOH and I. KOMAKI .....	651
Direct Analysis of Tramp Elements in Steel by Radio-frequency Glow Discharge Optical Emission Spectrometry Associated with Bias-current Introduction	
—The Application to Quantitative Determination of Tin— (Technical Report)	
K. WAGATSUMA .....	694

### Surface Treatment and Corrosion

Microbially Influenced Corrosion and Biodeterioration of Structural Metals (Review)	
Y. KIKUCHI and K. R. SREEKUMARI .....	620
Microbiologically Influenced Corrosion of SUS304L and SUS316L Welds Caused by Aerobic and Anaerobic Bacteria in Groundwater (I)	
—Laboratory Simulation Studies and Corrosion Behavior—	
Y. KIKUCHI, M. OZAWA, K. TOHMOTO, H. ONISHI, T. SAKANE and T. ANZAI .....	658
Microbiologically Influenced Corrosion of SUS304L and SUS316L Welds Caused by Aerobic and Anaerobic Bacteria in Groundwater (II)	
—A Role of Aerobic and Anaerobic Bacteria—	
Y. KIKUCHI, M. OZAWA, K. TOHMOTO, H. ONISHI, T. SAKANE and T. ANZAI .....	664
Effect of Alloy Elements on Localized Corrosion Characteristics of Nitrogen-bearing Stainless Steels and Evaluation of Crevice Corrosion in Seawater Environment/M. SAGARA, H. UNO, Y. KATADA and T. KODAMA .....	672

### Transformations and Microstructures

Effect of B on Microstructural Change during Creep Deformation in High Cr Ferritic Heat Resistant Steel/T. AZUMA, K. MIKI, Y. TANAKA and T. ISHIGURO .....	678
Precipitation Behavior of TaC in Austenite of Ferritic Heat Resisting Steel with High Chromium Contents	
K. SHINOZUKA, M. TAMURA and H. ESAKA .....	686